IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

INVENTORS:

Tatsuhisa YOKOI, et al.

Confirmation No. 5810

SERIAL NO:

10/589,204

FILING DATE:

11 August 2006

TITLE:

REGENERATION CONTROLLER FOR EXHAUST PURIFICATION

APPARATUS OF INTERNAL COMBUSTION ENGINE

PATENT NO.:

7,841,169 B2 Issued 30 November 2010

CERTIFICATE OF CORRECTION BRANCH

COMMISSIONER FOR PATENTS

P. O. Box 1450

Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 C.F.R § 1.323

SIR:

It is respectfully requested that the enclosed certificate of correction be issued for the above Patent under authority of 35 USC § 355.

The changes represent correction of minor errors on the part of the applicants.

The fee under 37 C.F.R. 1.20(a) in the amount of \$100.00 is being paid by credit card.

If a petition to correct any of the errors is required, please considered this such a petition and charge the fee to Deposit Account No. 11-0600.

Respectfully submitted,

Dated: 24 March 2011

/Shawn W. O'Dowd/ Shawn W. O'Dowd (Reg. No. 34,687)

KENYON & KENYON LLP 1500 K Street, N.W., Suite 700 Washington, DC 20005

Tel: (202) 220-4200 Fax: (202) 220-4201

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

7,841,169 B2

Page 1 of 1

DATED

30 November 2010

FILED

11 August 2006

INVENTOR(S):

Tatsuhisa YOKOI, et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column	<u>Line</u>	
8	55	Change "intermittent has" tointermittent
		addition has
18	62	After "flows" insertin
19	45	Change "less that" toless than
20	3	After "portion" insertof
20	19	Change "less that" toless than
22	20	After "flows" insertin

MAILING ADDRESS OF SENDER:

Shawn W. O'Dowd KENYON & KENYON LLP 1500 K Street, N.W., Suite 700 Washington, DC 20005 Patent No.: 7,841,169 B2